

00772007-091001





FIG. 1








FIG. 3

09777007-091001



0077007-001001



Drain Side Program Rate Distribution After UV Erase




FIG. 6

Source Side Program Rate Distribution After UV Erase




Fig 7

FOOTNOTES: 20022260




FIG 8

FOOTED 2007/07/26




FIG. 9